



These tiles etc may move, or be displaced, in particular when the vertical face of the sill is minimal, thus not allowing much room for the sand and cement bed to be placed before installing the sill tile.





KORDON TERMITE BARRIER

Subject Sheet No.

door / sill - detail 1

kd 048b