



Note:
the sketch above shows a renovation
to an existing building

it is strongly recommended that the existing
building has a termite inspection before
any new works.

 **KORDON TERMITE BARRIER**

Subject

Sheet No.

retaining wall - detail 1

kd 021